Technical Bulletin

Bulletin No: TCH-013-008 **Effective Date: 9/24/04** **Cancels: N/A** **Page: 1 of 1**

Subject: **Bendix® is Replacing WS-20™ with WS-24™ Antilock Wheel Speed Sensors**

90 DEGREE BENDIX® WS-24™ WHEEL SPEED SENSOR

STRAIGHT BENDIX® WS-24™ WHEEL SPEED SENSOR

PREVIOUS BENDIX WHEEL SPEED SENSORS

The WS-24™ sensor fit and function is compatible with all previous Bendix wheel speed sensors.

FIGURE 1 - ***WHEEL SPEED SENSORS***

As a product improvement, Bendix® WS-20™ wheel speed sensors are being replaced by the new WS-24™ wheel speed sensors.

Please note that WS-24™ wheel speed sensors must use clamping sleeve p/n 5012878 instead of p/n 5006849. Always use correct clamping sleeves to avoid problems associated with reduced retention force, such as sensor movement and resulting ABS trouble codes.

The fit and function of the WS-24™ wheel speed sensor is compatible with all previous Bendix sensors.

Reference

Order Service Data sheets (by BW number) or download them from www.bendix.com. The Service Data sheet for Bendix® WS-24™ wheel speed sensors is SD-13-4860 (BW2364), and for Bendix® WS-20™ wheel speed sensors use SD-13-4754 (BW1662).



FIGURE 2 - ***PREVIOUS AND NEW CLAMPING SLEEVES***

© 2004 Bendix Commercial Vehicle Systems LLC 9/2004. All Rights Reserved. Printed in U.S.A.